
3. Click **Next** to confirm that you want to install the tool.




4. On the Select Installation Folder screen, select the folder where you would like the tool installed. Click **Next**.



5. Wait while the tool instals




6. When the installation is complete, click **Close**.



ALTERNATE LOW METER TOOL INSTALLATION METHOD

If the CD d es not automatically open:

- 1. Navis to a the CD disk location.
- 2. Lick on the **Badger Meter Flow Meter Tool 1.1** folder to open it.
- 3 Double-click the **index.htm** file to open it.
- On the Flow Meter Tool window, select Click here to run installer of Flow Meter tool.



5. Perform Steps 3 through 6 under "Installing the Flow Meter Tool" in this document to complete the installation.